


MG12FI, MG12FT

It's ideal for quick estimating jobs. Automatically records measurements line to line, wall to wall, vertically, overhead, around curves and over contours. You don't need a helper to hold the end of the tape for all indoors and outdoors measuring. You measure when you want to, counter total is always in view.

SPECIFICATION OF " MEASURING WHEELS "

MODEL NO.	NO. OF WHEELS	MIN. UNIT	MAX. DISTANCE	DIA. OF WHEELS	CIRCUMFERENCE OF WHEELS	RESET SYSTEM	PACKING	N.W./G.W./CU. FT
MG12FI	1	1 INCH	10,000 FEET	3.82 INCHES	12 INCHES	KNOB	1PC/BOX,6PCS/CTN.	2.5KGS/8KGS/1.65'
MG12FT	1	0.1 FOOT	10,000 FEET	3.82 INCHES	12 INCHES	KNOB	1PC/BOX,6PCS/CTN.	2.5KGS/8KGS/1.65'

REMARK : *MG = MEASURE GUIDE® *FI=FEET/INCHES *FT=FEET/TENTHS *EACH PIECE HAS A CARRYING BAG.



MG10MC, MG10MD

Carry it everywhere! So quick and easy to use, just set the counter to zero and start walking, as long as you are walking, you are measuring. The sturdy telescoping handle adjusts to fit the individual. To reset at any time simply push the reset button. Adds forward and subtracts in reverse. Especially suited to long indoor runs such as plant floor plans or outdoor measuring on firm surfaces.

SPECIFICATION OF " MEASURING WHEELS "

MODEL NO.	NO. OF WHEELS	MIN. UNIT	MAX. DISTANCE	DIA. OF WHEELS	CIRCUMFERENCE OF WHEELS	RESET SYSTEM	PACKING	N.W./G.W./CU. FT
MG10MC	1	5 CM	10,000 METERS	159.16 MM	50 CM	PUSH BUTTON	1PC/BOX,6PCS/CTN.	3.6KGS/10.5KGS/2.85'
MG10MD	1	1 DM	10,000 METERS	159.16 MM	50 CM	PUSH BUTTON	1PC/BOX,6PCS/CTN.	3.6KGS/10.5KGS/2.85'

REMARK : *MG = MEASURE GUIDE® *MC=METERS/CENTIMETERS *MD=METERS/DECIMETERS *EACH PIECE HAS A CARRYING BAG.